

# Sales Detail by Association by Customer by Type

From 1/1/2009 To 3/31/2009

PO Date	PO #	Date In	Date Out	Invoice #	Repair #	Manuf	Model#	Serial #	Invoice \$	Work Done
<b>Flexible</b>										
11/13/2008		11/13/200	1/19/2009	140197	135490	Fujinon	XL-4400	4S081A244	\$0.00	Courtesy; Reset.
11/13/2008		11/13/200	1/19/2009	140206	135491	Fujinon	VP-4400	4V395A244	\$0.00	Eval Ok
2/17/2009	NONE	2/17/2009	2/20/2009	141771	136495	Fujinon	EG450WR5	1G201A40	\$75.00	Replace bending rubber seals, clean and polish both cover glass.
2/27/2009	109746	2/27/2009	3/12/2009	142718	136595	Fujinon	EG450WR5	1G201A65	\$1,329.00	Replace nozzle, replace bending rubber, replace
2/27/2009	109746	2/27/2009	3/12/2009	142718	136595	Fujinon	EG450WR5	1G201A65	\$0.00	Replace VCA.
<b>Flexible TOTAL</b>									\$1,404.00	
<b>TOTAL</b>									\$1,404.00	